

- ❖ Testing laboratory according to Regulation (EU) Nr. 305/2011, notified body No.: NB 1625
- ❖ Testing laboratory according to DIN EN ISO/IEC 17025:2005, DAkkS No. D-PL-17727-01-00
- ❖ Testing, monitoring and certification body according to LBO, registered No.: NRW 15
- ❖ Testing, monitoring and certification body in construction supervision licensing procedures
- ❖ DIN CERTCO testing laboratory, registered No. PL139

Test report: Enclosed wood heater – smoke emission

Test methods	Norsk Standards: NS 3058-1: June 1994 NS 3058-2: June 1994 NS 3059: October 1994
Testing station	RRF Rhein-Ruhr Feuerstätten Prüfstelle GmbH Im Lipperfeld 34 b D-46047 Oberhausen Telefon: +49(0)208-607041 - 0, Fax: +49(0)208-607041 - 28
Reference No.	RRF - NS 14 3598
Manufacturer	Thorma Výroba k.s. Šávolská cesta 1, SK - 986 01 Fil'akovo
Product name Type, Serial number	Wood heater Andorra Andorra Exclusive, Cadiz, Cordoba, Delia, Maldorra, Sevilla and Rodano
Client	Thorma Výroba k.s. Šávolská cesta 1, SK - 986 01 Fil'akovo
Date of delivery	17.04.2014
Taking of the appliance	Delivered by manufacturer
Leakage of the wood heater (at +25 Pa)	12 m ³ /h
Total weighted particulate emission	2,03 g/kg dried wood
Test location	Voßhölzchen 10, 57489 Drolshagen
Technician	Droll, D.

Abstract:

The wood heater Andorra fulfils the Norwegian requirements for smoke emission according to NS 3059 grade 2 and the requirements according to EN 13240 approved in the testing laboratory Rhein-Ruhr Feuerstätten Prüfstelle, test report No. RRF - 40 09 1930, dated on 20.04.2009.

This test report has been drawn up without prejudice to the rights of third parties in respect of private trademark rights of the initiator or manufacturer and may not be published in extracts.

The test report consisting of pages 1 to 28 and the appended test documentation a to q contain the results of the testing relating to this standard.

Oberhausen, 16 June 2014
(place and date)



(Dipl.-Ing. S. Müller)
(stamp and signature of Head of Testing Laboratory)